Weather tration Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0871/1

Work Order Type: Weatherization Audit Name: 17017UC-0871

CLIENT INFORMATION

Client ID: 17017UC-0871

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:
Cookeville, TN 38506 Email Address:

Agency Contact: Patterson, Danny Work Phone:

Cell Phone: (931) 261-1664

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1973 SITE BUILT HOME

Measures

•	Measure 1		l new door slab, weat o threshold and jam s va		th	Componen	ıts			Inspected
C	omment									
			Estimated			Actual				
#	Material / Lab	oor l	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Ī	Misc Material	Each	1					
C	Other Detail									
					Measur	e Sub Total:			Sub Total:	
C			Ducts ir ducts with mastic x 1 x inside return air vent			Componen				Inspected
	comment Se Se	al/repai al/caulk	ir ducts with mastic x 1 k inside return air vent	Unite	<u> </u>	Estimated	<u> </u>	Otiv	Actual	
#	omment Se	al/repai al/caulk	ir ducts with mastic x 1	<i>Units</i> Each	Qty 1	·		Qty		Inspected Total
# 10	Comment Se Se Material / Lab Miscellaneou	al/repai al/caulk	ir ducts with mastic x 1 inside return air vent		_	Estimated	<u> </u>	Qty	Actual	
# 10	Comment Se Se Material / Lab Miscellaneou Supplies	al/repai al/caulk	ir ducts with mastic x 1 inside return air vent		_	Estimated	<u> </u>	Qty	Actual	
# 10	Comment Se Se Material / Lab Miscellaneou Supplies	al/repai al/caulk	ir ducts with mastic x 1 inside return air vent		_	Estimated	<u> </u>	Qty	Actual	
# 10	Comment Se Se Material / Lab Miscellaneou Supplies	al/repai al/caulk	ir ducts with mastic x 1 inside return air vent	Each	1	Estimated	<u> </u>		Actual	

Measure 3 DW	H Pipe Insulation			Componen	its			Inspected
Comment		Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	wrap water pipes							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measure Sub Total:				Sub Total:	
Measure 4 Floor Ins. R-19 Comment			Components FL Estimated			Inspected Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1092					
Other Detail						,		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Inspected **Measure 5** REPLACE UNVEMTED GAS HEATER **Components** WITH VENTED GAS HEATER Comment MUST REPLACE UNVENTED GAS HEATER BEFORE ANY WORK CAN BE PERFORMED ON HOME. Estimated Actual # Material / Labor **Unit Cost Unit Cost Description / Comment** Units Total Qty **Total** Qty 10 Unspecified Misc Material Each 1 Other Detail Sub Total: Measure Sub Total: Field Notes: Inspected Measure 6 Smoke Detector is Needed **Components Comment Estimated** Actual # Material / Labor **Description / Comment Unit Cost Unit Cost** Total Units Qty Total Qty Health and Safety 9-volt Smoke Detector Each 1 Items 2 Labor Labor Hour Other Detail Sub Total: Measure Sub Total:

Work Order Grand Total: Grand Total:

Field Notes: